

- Not-Public Document – Not For Public Disclosure
- Public Document – Not-Public Data Has Been Excised
- Public Document

Xcel Energy Data Request No. 1-1
 Docket No.: EL23-029
 Response To: South Dakota Public Utilities Commission
 Requestor: Joseph Rezac
 Date Received: January 12, 2024

Question:

In reverence to Exhibits C1/C2 Lines 27-29, provide an explanation as to why the southeast corner of the NE1/4 of the NE1/4 of Section 17 of T101N, R48W, is not the same point as the southwest corner of the NW1/4 of the NW1/4 of Section 16 of T101N, R48W.

Response:

The response is per Gene Maurice, principal professional land surveyor, at Sayre Associates who assisted in providing exhibits for the docket. A local land surveyor surveyed and used the existing fence line as the 1/4 1/4 section and platted the same with other lots instead of splitting the section correctly. The section to the east was correctly surveyed and split-up as shown on the exhibit, which reflects the distance of approximately 42' for the true 1/4 1/4 corner.

Preparer:	Eric Pauli	Tim McCarthy
Title:	Manager, Community Relations	General Manager/CEO
Department:	NSPM SD Jurisdiction	Sioux Valley Southwestern Electric
Telephone:	605.333.8381	605.534.3535
Date:	January 24, 2024	January 24, 2024